

From: Michiteru Kato/=HINPO/TMC0. Sent:5/10/2007 1:49 AM.  
To: [-] Chris Santucci/=WDC/Toyota\_NY@TOYOTA\_NY@TOYOTA@TMCE.  
Cc: [-] Kirk Forsht/=TMS/Toyota@Toyota@TMCE;George Morino/=TMS/Toyota@TOYOTA.  
Bcc: [-] .  
Subject: Re: Fw: PE07016 VOQs.

Chris,

I looked over the NHTSA complaints on 2007 Camry and Avalon, I found 2 complaints which might be related to the mat.

10188142(Avalon)

10171354(Camry)

Let's discuss next week.

Thanks,

Mitch

宛先: Michiteru Kato/HINPO/TMC0@TMC0@TMCE@TOYOTA

cc: Kirk Forsht/TMS/Toyota@Toyota

件名: Fw: PE07016 VOQs

Mitch,

FYI: Updated VOQ's from NHTSA. I haven't read through them yet, but please, take a look and see his comments about Camry/Avalon.

Regards,

Chris Santucci - Assistant Manager  
Technical and Regulatory Affairs  
Toyota Motor North America, Inc.  
Ofc (202) 463-6856 Cell (202) 651-1581 Fax (202) 463-8513  
email: Chris\_Santucci@tma.toyota.com

Note: We cannot receive attachment extensions listed below.

.exe, .com, .pif, .scr, .cmd, .bat, .vbs, .lnk, .htm, .html, .shs, or .zip

----- Forwarded by Chris Santucci/WDC/Toyota\_NY on 05/08/2007 03:03 PM -----

<Scott.Yon@dot.gov>

05/08/2007 11:21 AM

To <CSantucci@tma.toyota.com>

cc <Jeff.Quandt@dot.gov>, <Bill.Collins@dot.gov>

Subject PE07016 VOQs

Chris,

Can you confirm you have received this message and the 9 attachments please?

Per our discussion this morning here is the current status of VOQs for PE07-016.

Opened on: 10180658, 10182245, 10182749, 10183821, and 10186045. Copies of VOQs provided previously.

Now considering/reviewing: 10174071, 10174732/10176450 (two VOQs, same incident), 10186045, 10189487, 10189528, and 10189655

Note: 10189655 resulted in airbag deployment which we assume means there may be some EDR/CDR data stored. ODI may want to discuss this further with Toyota.

Also, ODI 10188471 is a duplicate for 10182749 (counted in open, same incident).

I have provided un-redacted copies of each of the 'new' reports (and any related documents) for your review.

There are a few 2007 Camry VOQs and a 2007 Avalon VOQ which may be related to all weather mats although these are currently out of scope.

Regards,  
Scott

D. Scott Yon  
U.S. Department of Transportation  
National Highway Traffic Safety Administration  
Office of Defects Investigation  
Room 5326-I  
400 7th Street S.W.  
Washington, DC  
20590  
202-366-0139  
fax-202-366-1767

-----  
The information contained in this e-mail message has been sent from a federal agency of the United States Government. It may be privileged, confidential, and/or protected from disclosure. If you are not the intended recipient, any further disclosure or use, dissemination, distribution, or copying this message or any attachment is strictly prohibited. If you think that you have received this e-mail message in error, please delete it and notify the sender.  
=====